

# TiO Software Suite Release Notes

July 13, 2016

## Element Software Version Numbers

---

### Software Suite Version: 3.4.0

Includes:

MC2 Version:	3.40
Audio Version:	4.20
Lighting Version	2.10
Android App Version:	3.4.0
iPad App Version	3.5.0

To see the current software versions of the Elements in your system, access the “Manage Your Elements” page from the Main Settings page in the TiO Pro app. All Elements will be listed and the version for each is shown.

Summary: TiO 3.4.0 is a mid-level software update that adds shade control (open, close and stop action) from a TL4, over-the-air updates for the TCWIFI and TCIP devices, and ability to hide TL4's from the control screen that are not connected to a physical load (e.g. 3, 4, 5 way).

How to get the update: All TiO Home application updates are obtained by downloading the new version of the app from the Google Play Store or the Apple Store.

## New Features and Improvements in Software Suite 3.4.0

---

1. **TiOConnect** product interface additions
  - a. None in this release
2. **Audio** System Changes/Improvements
  - a. Various bug fixes
3. **Master Coordinator** Changes/Improvements
  - a. Added ability to automatically update TCWIFI and TCIP devices over-the-air
  - b. Removed backlight issue from mood state
  - c. Fixed issue where multiple timed experiences could lock up MC2
  - d. Fixed mood issue where system would stop activating moods
  - e. Fixed alternating dimming issue when minimum load was greater than 0
4. **Lighting** Changes/Improvements
  - a. Removed backlight from mood state
  - b. Fixed backlight issue during pairing
  - c. Fixed sporadic issue with moods not executing

- d. Fixed alternating dimming issue when minimum load was greater than 0
5. **TiO Android** App (Phones/Tablets with Android 4.2 or later) Changes/Improvements
- a. Added ability to hide TL4's from control screen that are not connected to a physical load
  - b. Shades open, close, stop actions can be added to button assignments
  - c. Display TCWIFI & TCIP versions on system settings page and manage elements page
  - d. Various bug fixes
6. **TiO iOS** App (iPhones, iPads)
- a. Added ability to hide TL4's from control screen that are not connected to a physical load
  - b. Shades open, close, stop actions can be added to button assignments
  - c. Display TCWIFI & TCIP versions on system settings page and manage elements page
  - d. Various bug fixes

## Known Issues in Software Suite 3.4.0

---

### TiOConnect

1. Honeywell Security Panel Interface

When a Honeywell/Ademco security system is initially configured, the TiO App must be restarted for the room names to appear

### Android App

No Known issues

### iOS App

No Known issues

### Audio

1. UPnP Working on TiO network only. Does not bridge from home owner's network. Album art will display if the cover image is stored in the same folder as the music and named cover.jpg.

### Lighting

1. Pairing a TL4 with a new MC when the TL4 has been previously paired with a different MC may require manual activation of the Pairing Mode. Hold both top and bottom buttons for approximately 5 seconds until a double click is heard. After about a minute, the backlight will begin pulsing quickly, indicating that the TL4 is in Pairing Mode. Please follow the automatic association process to pair the TL4 to the new MC.

### Climate

1. Climate Display Refresh

When interfacing with a Nest Thermostat, the inside temperature and Humidity displays are updated every 90 seconds per Nest requirements.

2. No beacon support for Nest Thermostats

TiO cannot beacon a Nest Thermostat from the Manage Elements screen.

### System Setup

No Known issues